

# INSPECTION REPORT



For the Property at:  
**1600 N. PAULINA ST.**  
CHICAGO, IL 60622

---

Prepared for: MARTHA BLACK and CARL FINN  
Inspection Date: Monday, September 9, 2013  
Prepared by: Thomas Jansson



Acuity Home Inspection Service  
1936 W Estes Ave  
Chicago, IL 60626  
312-217-5249  
IL Lic. 450.003340 exp 11/30/14  
[www.insightinspec.com](http://www.insightinspec.com)  
[tj@insightinspec.com](mailto:tj@insightinspec.com)



January 5, 2014

Dear Martha Black and Carl Finn,

RE: Report No. 1392, v.2  
1600 N. Paulina St.  
Chicago, IL  
60622

Thank you for choosing Acuity. If you have questions about your inspection or report, please let me know. You can always e-mail me at [tj@insightinspec.com](mailto:tj@insightinspec.com). The fastest way to reach me is usually my cell: 312.217.5249.

This is an interactive report. Many of the items have blue hyperlinks which connect you to a home inspection database. To navigate quickly between sections, use the tabs at the top of the page.

Where action is recommended, only licensed and insured specialty contractors should be used. When researching costs, you are encouraged to obtain three signed estimates from three different, licensed and insured contractors. Always be sure to compare "apples to apples." Price disparities may indicate different levels of workmanship, design, or materials.

Contractors may uncover additional issues that were not detected or discussed at the inspection. This isn't unusual. Home inspections are non-invasive, non-destructive, limited, visual inspections, performed by a generalist. A specialist will have more detailed knowledge in his or her particular field, and may be authorized to perform certain tasks that a home inspector, performing a normal home inspection, would never do (like removing a wall, spending an hour under a sink, or disassembling the furnace.)

The inspection is a "snapshot in time." It's a look at the house as it appeared on inspection day. Ongoing maintenance, and ongoing monitoring, are important parts of home ownership. There's no such thing as a "maintenance-free" house.

Sincerely,

Thomas Jansson  
on behalf of  
Acuity Home Inspection Service

Acuity Home Inspection Service  
1936 W Estes Ave  
Chicago, IL 60626  
312-217-5249  
IL Lic. 450.003340 exp 11/30/14  
[www.insightinspec.com](http://www.insightinspec.com)  
[tj@insightinspec.com](mailto:tj@insightinspec.com)

# SUMMARY

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

**Note:** For the purpose of this report the building is considered to be facing **West**.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

## Roofing

### FLAT ROOFING \ Modified bitumen

**Condition:** • [Leak](#)

Active leak at GARAGE. Immediate repair by licensed roofing contractor is needed. See additional notes in "Structure."

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** East (Garage)

**Task:** Repair

**Time:** Immediate

**Condition:** • [Patched](#)

Open seams have been patched over with roofing cement. This appears to be a temporary solution that could fail at any time. Review and repair by licensed roofing contractor is recommended prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** West (House)

**Task:** Further review by licensed roofing contractor; Repair

**Time:** Immediate

### FLAT ROOF FLASHINGS \ Flashings

**Condition:** • Inspect during annual tune-up

Frequent inspection and maintenance of this type of flashing is necessary. The caulk has a tendency to dry and crack, leading to roofing leaks. An annual maintenance check by a licensed roofing contractor is recommended.

**Location:** Roof Flashings

**Task:** Service

**Time:** Immediate

### FLAT ROOF FLASHINGS \ Installation

**Condition:** • [Missing, too short](#)

No flashing at air conditioning lines. Chance of water entry. Area appeared free of leaks, but is considered vulnerable. The addition of a pitch pan is recommended. Consult with licensed roofer prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

## Exterior

### ROOF DRAINAGE \ Downspouts

**Condition:** • [Loose connections](#)

**Implication(s):** Leakage

**Location:** North

**Task:** Correct

**Time:** Immediate

# SUMMARY

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## WALLS \ Flashings and caulking

**Condition:** • No flashing or drip edge noted at parapet cap. Lack of these features has been known to lead to water entering the wall cavity in this type of construction. No significant interior water penetration was observed at time of inspection.

## WALLS \ Brick, stone and concrete

**Condition:** • [Mortar deterioration](#)

Mortar cracks noted at parapet and at parapet caps. All exterior masonry should be sealed and waterproofed by licensed and insured masonry specialist prior to closing.

**Implication(s):** Chance of water entering house | Weakened structure | Chance of structural movement

**Condition:** • [Mortar deterioration](#)

Mortar cracks were noted throughout exterior. Even small cracks such as these can allow significant amounts of water into the structure. Testing with RILEM tubes at a representative section of the south wall revealed that the exterior is extremely vulnerable to water entry. Further evaluation and repair by licensed and insured split-faced block specialist is strongly recommended prior to closing.

**Implication(s):** Chance of water entering house | Weakened structure | Chance of structural movement

## EXTERIOR GLASS \ Exterior trim

**Condition:** • [Caulking loose, missing or deteriorated](#)

Maintaining the integrity of the exterior caulk is essential to prevent water from entering the building envelope. Have doors and windows throughout reviewed and re-caulked as needed by licensed and insured exterior waterproofing specialist prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Increased heating and cooling costs

**Location:** Throughout

**Task:** Repair

**Time:** Immediate

## Structure

### ROOF FRAMING \ Rafters/trusses

**Condition:** • [Concentrated loads](#)

Point loads have been attached to trusses for storage shelving support. Please be aware that trusses are engineered components; they may or may not be designed to bear weight from below. Further evaluation by licensed structural engineer, or removal of point loads is recommended prior to closing.

**Implication(s):** Chance of structural movement

**Location:** Garage

**Condition:** • [Rot](#)

Rot noted at garage truss. Further evaluation is recommended when repairing garage roof. Replacement of damaged truss(es) may be necessary. Have trusses evaluated by licensed roofer or licensed structural engineer prior to closing.

**Implication(s):** Weakened structure

**Location:** Garage

# SUMMARY

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## ROOF FRAMING \ Sheathing

**Condition:** • [Water stains](#)

Water stains, elevated moisture levels noted at garage roof sheathing, southeast. Replace damaged sheathing when repairing roof.

**Implication(s):** Material deterioration

**Location:** Garage

## Electrical

### SERVICE DROP AND SERVICE ENTRANCE \ Service drop

**Condition:** • [Height over balcony](#)

Improper clearance from balcony. 5 foot horizontal clearance is recommended. Have service entrance moved when correcting meter base issue noted elsewhere in this section.

**Implication(s):** Electric shock

### SERVICE BOX, GROUNDING AND PANEL \ Service box

**Condition:** • [Box location poor](#)

Meter socket is at grade. ComEd requires 30" minimum clearance from grade to meter base (ComEd Residential Electric Service Installation Guide, 5th Edition, page 28). Have meter base height corrected by licensed electrician per ComEd requirements prior to closing.

**Implication(s):** Difficult access | Difficult to service

### DISTRIBUTION SYSTEM \ Wiring - installation

**Condition:** • [Open splices](#)

Exposed splices in garage. Have wire properly enclosed by licensed electrician prior to closing.

**Implication(s):** Electric shock | Fire hazard

### DISTRIBUTION SYSTEM \ Lights

**Condition:** • [Improper closet lighting](#)

Bare bulbs in closets are a potential fire hazard. All closet lighting fixtures should be repaired or replaced. Have appropriate fixtures installed by licensed electrician in accordance with current national standards prior to closing.

**Implication(s):** Fire hazard

**Location:** East basement bedroom

**Task:** Replace closet lighting

**Time:** Immediate

### DISTRIBUTION SYSTEM \ Outlets (receptacles)

**Condition:** • [GFI test faulty](#)

**Implication(s):** Electric shock

**Location:** Rooftop, East

**Task:** Replace Faulty GFCI

**Time:** Immediate

# SUMMARY

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspec.com](http://www.insightinspec.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

**Condition:** • Arc Fault Interrupter (AFI) needed

Current national standards require Arc Fault Interrupter (AFI) outlets for all bedroom outlet circuits. Have AFI breakers added as needed by licensed electrician to enhance the safety of the electrical system.

See APPENDIX for more information on AFCI protection.

## Plumbing

### WATER HEATER \ Temperature/pressure relief valve

**Condition:** • TPR Discharge Tube Issues: The discharge tube should be as short and as straight as possible, ending at approximately 6" above the floor. The end of the tube should be uncapped, unthreaded, and readily visible.

Tube not straight; termination not visible. Have corrected by licensed plumber prior to occupancy.

**Location:** Water Heater

**Task:** Correct

**Time:** Immediate

### WASTE PLUMBING \ Sewage ejector pump

**Condition:** • [Odor](#)

Strong odor noted at ejector pump, north-east plumbing closet, basement. Presence of air admittance valve (AAV) raises questions of a possibly inadequate venting installation. No vents were observed at north side of roof. (may have been obscured by rooftop planters, etc.; presence of venting could not be confirmed). Have ejector and venting checked and repaired as needed by licensed plumbing contractor prior to closing.

**Implication(s):** Sewer gases entering the house

### FIXTURES AND FAUCETS \ Toilet

**Condition:** • [Loose](#)

Loose toilets. Have licensed and insured plumbing contractor replace wax ring and re-seat loose toilet prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Sewage entering the house

**Location:** East basement bathroom, Master bathroom, Second floor west bathroom, First floor powder room

**Task:** Repair

**Time:** Immediate

### FIXTURES AND FAUCETS \ Shower stall

**Condition:** • Inoperative

Inoperative Rain Shower. Have checked and repaired as needed by licensed plumber prior to closing.

**Location:** Master bathroom shower stall

**Task:** Repair

**Time:** Immediate

### FIXTURES AND FAUCETS \ Shower stall enclosure

**Condition:** • [Leak](#)

Leak at master shower stall enclosure. Have repaired as needed by licensed shower stall specialist prior to use.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Master Bathroom

**Task:** Repair

**Time:** Immediate

# SUMMARY

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## Interior

### WINDOWS \ Means of egress

**Condition:** • [Too small](#)

Second floor middle bedroom: windows are too small to conform to current national standards regarding rescue opening in case of emergency.

Basement bedrooms: Windows too high from finished floor surface to conform to current national standards for emergency rescue openings.

**Implication(s):** Restricted emergency exits

### STAIRS \ Handrails

**Condition:** • [Missing](#)

Handrails and guardrails missing throughout. Guardrails at main stairway hazardous to children. All stairways should be reviewed and corrected as needed by licensed contractor prior to occupancy.

**Implication(s):** Fall hazard

**Location:** Throughout

**Task:** Correct

**Time:** Immediate

This is the end of the summary section. The remainder of the report deals with individual systems in more detail, and may list conditions that were not included in the summary section. Please read the entire report.

# ROOFING

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## Description

**General:** • The Description section identifies components in the home by material or type. This is provided as an inventory, and no observations or comments on conditions are included here.

**Flat roofing material:**

- [Roll roofing](#)

Modified Bitumen Torch-Down Roof

**Probability of leakage:** • Medium

## Limitations

**Roof inspection limited/prevented by:** • Deck/solar panels covering roof

**Inspection performed:** • By walking on roof

## Recommendations

**General**

• Roofs may leak at any time. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. A roof leak does not necessarily mean the roof has to be replaced. We recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of roofs.

**FLAT ROOFING \ Modified bitumen**

**Condition:** • [Leak](#)

Active leak at GARAGE. Immediate repair by licensed roofing contractor is needed. See additional notes in "Structure."

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** East (Garage)

**Task:** Repair

**Time:** Immediate

**Condition:** • [Patched](#)

Open seams have been patched over with roofing cement. This appears to be a temporary solution that could fail at any time. Review and repair by licensed roofing contractor is recommended prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** West (House)

**Task:** Further review by licensed roofing contractor; Repair

**Time:** Immediate



# ROOFING

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspec.com](http://www.insightinspec.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING


COOLING

PLUMBING

INTERIOR

APPENDIX

## Damaged and patched flat roofs



[Click on image to enlarge.](#)



*Patched*

**Condition:** • [No UV protection \(paint, granules, etc.\)](#)

Have licensed roofing contractor apply appropriate UV sealant to flat roof sections prior to closing. Lack of UV protection decreases flat roof life.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

# ROOFING

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX



*No UV protection (paint, granules, etc.)*

## **FLAT ROOF FLASHINGS \ Flashings**

**Condition:** • Inspect during annual tune-up

Frequent inspection and maintenance of this type of flashing is necessary. The caulk has a tendency to dry and crack, leading to roofing leaks. An annual maintenance check by a licensed roofing contractor is recommended.

**Location:** Roof Flashings

**Task:** Service

**Time:** Immediate



*Previous repair to roof flashing*



*Service needed at roof flashing*

## **FLAT ROOF FLASHINGS \ Installation**

**Condition:** • [Missing, too short](#)

No flashing at air conditioning lines. Chance of water entry. Area appeared free of leaks, but is considered vulnerable. The addition of a pitch pan is recommended. Consult with licensed roofer prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

# ROOFING

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX



*No flashing, previous repair, vulnerable area*



*Missing flashing; vulnerable to leakage*

# EXTERIOR

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## Description

Gutter & downspout material: • [Aluminum](#)

Gutter & downspout type: • [Scuppers](#)

Gutter & downspout discharge: • [Below grade](#)

Lot slope: • [Flat](#)

Wall surfaces - masonry: • [Artificial stone](#) • [Block](#)

Walkway: • Concrete

Exterior steps: • Stone

Garage: • Masonry Block

## Limitations

Upper floors inspected from: • Ground level

Exterior inspected from: • Ground level

## Recommendations

### ROOF DRAINAGE \ Downspouts

Condition: • [Loose connections](#)

Implication(s): Leakage

Location: North

Task: Correct

Time: Immediate



*Loose connection; may cause basement leaks*



# EXTERIOR

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## WALLS \ Flashings and caulking

**Condition:** • No flashing or drip edge noted at parapet cap. Lack of these features has been known to lead to water entering the wall cavity in this type of construction. No significant interior water penetration was observed at time of inspection.



*No flashing visible beneath sills throughout*



*No flashing seen under parapet caps thru-out*

**Condition:** • Flashing not visible throughout. Cannot verify the presence or absence of flashing between floors or at doors/windows.

Very small amounts of flashing were visible at ground level.

Inspector should be able to see flashing at all doors, all windows, and between floors. Complete, correctly installed flashing is necessary to keep water out of the interior structure and living space.

## WALLS \ Brick, stone and concrete

**Condition:** • Split face block (also known as split-faced concrete masonry units, or CMUs.) Problems with water penetration have been noted in other buildings using split-faced block. The irregular surfaces and natural porosity of the concrete make the CMUs vulnerable to water intrusion and damage to interior contents, structure and finishes. The block should be sealed with an appropriate waterproof coating for split-faced CMUs. Because of the nature of this job, and the importance of an effective water seal, only a licensed and insured masonry or waterproofing contractor should be used. Consult with a licensed masonry or waterproofing contractor prior to closing.

Water penetration has been linked to structural damage in other buildings of this type. Such structural issues were not observed at this inspection; however, this inspection was non-invasive and limited by the presence of interior finishes.

**Condition:** • [Mortar deterioration](#)

Mortar cracks noted at parapet and at parapet caps. All exterior masonry should be sealed and waterproofed by licensed and insured masonry specialist prior to closing.

**Implication(s):** Chance of water entering house | Weakened structure | Chance of structural movement

# EXTERIOR

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX



*Mortar deterioration at parapet wall*



*Mortar cracks at parapet caps*

**Condition:** • [Mortar deterioration](#)

Mortar cracks were noted throughout exterior. Even small cracks such as these can allow significant amounts of water into the structure. Testing with RILEM tubes at a representative section of the south wall revealed that the exterior is extremely vulnerable to water entry. Further evaluation and repair by licensed and insured split-faced block specialist is strongly recommended prior to closing.

**Implication(s):** Chance of water entering house | Weakened structure | Chance of structural movement



*Waterproofing needed*



*RILEM testing*

**EXTERIOR GLASS \ Exterior trim**

**Condition:** • [Caulking loose, missing or deteriorated](#)

Maintaining the integrity of the exterior caulk is essential to prevent water from entering the building envelope. Have doors and windows throughout reviewed and re-caulked as needed by licensed and insured exterior waterproofing specialist prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Increased heating and cooling costs

**Location:** Throughout



# EXTERIOR

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspec.com](http://www.insightinspec.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

**Task:** Repair

**Time:** Immediate



*Caulk deterioration throughout*



*Caulk deterioration throughout*

## DOORS \ Doors and frames

**Condition:** • [Rot](#)

Bottom portion of front door jamb is beginning to rot. Repair or replacement by licensed, skilled finish carpenter is recommended prior to closing.

**Implication(s):** Chance of damage to finishes and structure



*Rot: front door jamb exterior*

# EXTERIOR

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## DOORS \ Exterior trim

**Condition:** • [Damaged, cracked or loose](#)

Loose, damaged weather-stripping at rear patio doors. Chance of drafts, chance of water and pest entry. Have doors repaired as needed prior to closing.

**Implication(s):** Cosmetic defects | Chance of damage to finishes and structure



*Loose, damaged weather-stripping*

## PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Handrails and guards

**Condition:** • [Missing](#)

No handrails at south gangway stairs (x2)

Handrails not graspable at front stairway.

**Implication(s):** Fall hazard

**Location:** Exterior stairways throughout

**Task:** Correct

**Time:** Immediate



# EXTERIOR

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL


HEATING

COOLING


PLUMBING

INTERIOR

APPENDIX



[Click on image to enlarge.](#)



*Missing handrail*



*Handrail not graspable*

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## Description

**Configuration:** • [Basement](#)**Foundation material:** • [Poured concrete](#)**Floor construction:** • [Trusses](#)**Exterior wall construction:** • [Masonry](#)**Roof and ceiling framing:** • [Trusses](#) • Not visible

## Limitations

**Inspection limited/prevented by:** • Finished Basement**Inspection limited/prevented by:** • Wall, floor and ceiling coverings • Carpet/furnishings • Storage • New finishes/paint**Attic/roof space:** • No access**Percent of foundation not visible:** • 100 %

## Recommendations

### ROOF FRAMING \ Rafter/trusses

**Condition:** • [Concentrated loads](#)

Point loads have been attached to trusses for storage shelving support. Please be aware that trusses are engineered components; they may or may not be designed to bear weight from below. Further evaluation by licensed structural engineer, or removal of point loads is recommended prior to closing.

**Implication(s):** Chance of structural movement**Location:** Garage

*Concentrated loads on trusses*

# STRUCTURE

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## Condition: • [Rot](#)

Rot noted at garage truss. Further evaluation is recommended when repairing garage roof. Replacement of damaged truss(es) may be necessary. Have trusses evaluated by licensed roofer or licensed structural engineer prior to closing.

**Implication(s):** Weakened structure

**Location:** Garage



Garage: Water-stained sheathing



Water stains @ trusses throughout garage



Active water entry: Saturated Truss



Garage: Area of structural water damage





*Elevated moisture level; monitor; ongoing*



*Garage: Rotting Truss*

## **ROOF FRAMING \ Sheathing**

**Condition:** • [Water stains](#)

Water stains, elevated moisture levels noted at garage roof sheathing, southeast. Replace damaged sheathing when repairing roof.

**Implication(s):** Material deterioration

**Location:** Garage

## Description

**Service entrance cable and location:** • [Overhead](#)

**Service size:** • [200 Amps \(240 Volts\)](#)

**System grounding material and type:** • [Copper - water pipe](#) • [Not visible](#)

**Distribution panel type and location:** • [Breakers - basement](#)

**Distribution wire material and type:** • [Copper - conduit](#)

**Type and number of outlets (receptacles):** • [Grounded - typical](#)

**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • GFCI - Kitchen, Baths, Exterior

**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • No AFCI

**Smoke detectors:** • [Present](#)

**Carbon monoxide (CO) detectors:** • Present

## Limitations

**System ground:** • Continuity not verified • Quality of ground not determined

**Circuit labels:** • The accuracy of the circuit index (labels) was not verified.

## Recommendations

### General

• Any electrical recommendations should be considered high priority items, since all electrical issues are safety concerns.

### **SERVICE DROP AND SERVICE ENTRANCE \ Service drop**

**Condition:** • [Height over balcony](#)

Improper clearance from balcony. 5 foot horizontal clearance is recommended. Have service entrance moved when correcting meter base issue noted elsewhere in this section.

**Implication(s):** Electric shock



*Improper clearance from balcony to elec svc*

## SERVICE BOX, GROUNDING AND PANEL \ Service box

**Condition:** • [Box location poor](#)

Meter socket is at grade. ComEd requires 30" minimum clearance from grade to meter base (ComEd Residential Electric Service Installation Guide, 5th Edition, page 28). Have meter base height corrected by licensed electrician per ComEd requirements prior to closing.

**Implication(s):** Difficult access | Difficult to service



*Improper meter location*

## SERVICE BOX, GROUNDING AND PANEL \ Distribution panel

**Condition:** • Panel checked




*Panels checked*

## DISTRIBUTION SYSTEM \ Wiring - installation

**Condition:** • [Open splices](#)

Exposed splices in garage. Have wire properly enclosed by licensed electrician prior to closing.

**Implication(s):** Electric shock | Fire hazard



*Exposed wire splice at garage*

## DISTRIBUTION SYSTEM \ Lights

**Condition:** • [Improper closet lighting](#)

Bare bulbs in closets are a potential fire hazard. All closet lighting fixtures should be repaired or replaced. Have appropriate fixtures installed by licensed electrician in accordance with current national standards prior to closing.

**Implication(s):** Fire hazard

**Location:** East basement bedroom

**Task:** Replace closet lighting

**Time:** Immediate

## DISTRIBUTION SYSTEM \ Outlets (receptacles)

**Condition:** • [GFI test faulty](#)

**Implication(s):** Electric shock

**Location:** Rooftop, East

**Task:** Replace Faulty GFCI

**Time:** Immediate



# ELECTRICAL

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX



*Scorch marks on faulty GFI*



*GFI test faulty*

**Condition:** • Arc Fault Interrupter (AFI) needed

Current national standards require Arc Fault Interrupter (AFI) outlets for all bedroom outlet circuits. Have AFI breakers added as needed by licensed electrician to enhance the safety of the electrical system.

See APPENDIX for more information on AFCI protection.



# HEATING

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## Description

**Fuel/energy source:** • [Gas](#)

**System type:** • [Furnace](#)

**Furnace manufacturer:** • Tappan

**Heat distribution:** • [Ducts and registers](#)

**Efficiency:** • [High-efficiency](#)

**Approximate age:** • [11 years](#)

**Typical life expectancy:** • Furnace (high efficiency) 15 to 20 years

**Failure probability:** • [Medium](#)

**Exhaust pipe (vent connector):** • PVC plastic

**Fireplace:** • [Wood-burning fireplace](#) • [Gas fireplace](#)

**Chimney/vent:** • [Metal](#)

## Limitations

**Safety devices:** • Not tested as part of a building inspection

**Warm weather:** • Prevents testing heating effectiveness

**Heat loss calculations:** • Not done as part of a building inspection

**Fireplace/wood stove:** • Quality of chimney draw cannot be determined

**Heat exchanger:** • Only a small portion visible

## Recommendations

### GAS FURNACE \ Life expectancy

**Condition:** • Clean, Check And Service.

The furnace should be serviced annually, prior to the start of every heating season by a licensed HVAC contractor. Regular, routine maintenance will help to ensure maximum safety, efficiency, and service life.

# HEATING

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX



*Clean, Check, and Service Annually*

# COOLING & HEAT PUMP

1600 N. Paulina St., Chicago, IL September 9, 2013

Report No. 1392, v.2

[www.insightinspect.com](http://www.insightinspect.com)

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX

## Description

**Air conditioning type:** • [Air cooled](#)

**Manufacturer:** • Tappan

**Compressor approximate age:** • 11 years

**Failure probability:** • Compressor Life: The NAHB has found that air conditioners have an average life expectancy of 10-15 years. Again, this is a statistical average. Many units will either fall short or exceed this average. Factors include usage patterns, maintenance history, quality of installation, and original quality of the units themselves.

**Failure probability:** • [High](#)

## Limitations

**Heat gain/loss calculations:** • Heat gain and loss calculations are not performed as part of a home inspection. These calculations are typically performed by designers to determine the required size for heating and cooling systems prior to installation.

## Recommendations

### RECOMMENDATIONS \ Overview

**Condition:** • Annual maintenance by licensed HVAC technician is recommended to ensure system efficiency and maximum service life.

## Description

**Water supply source:** • Public

**Service piping into building:** • [Copper](#)

**Supply piping in building:** • [Copper](#)

**Main water shut off valve at the:** • Basement

**Water flow and pressure:** • [Functional](#)

**Water heater fuel/energy source:** • [Gas](#)

**Water heater type:** • [Induced draft](#)

**Water heater manufacturer:** • Bradford White

**Tank capacity:** • 75 gallons

**Water heater approximate age:** • 11 years

**Water heater failure probability:** • Water heater service life is given at 12 years. This is an average expectancy; like any mechanical device, there are units which greatly exceed the average life, and there are some that fail when still fairly new.

**Water heater failure probability:** • [High](#)

**Waste disposal system:** • [Public](#)

**Waste piping in building:** • [Plastic](#) • [Not visible](#)

**Pumps:** • [Solid waste pump \(ejector pump\)](#) • [Sump pump](#)

**Floor drain location:** • Near heating system

**Gas piping:** • Steel

## Limitations

**Inspection limited/prevented by:** • Access to sump pumps and sewage ejector pumps was severely limited due to presence of storage and personal items.

**Items excluded from a building inspection:** • Floor Drains • Sealed catch basins • Buried plumbing • Sprinkler Systems • Automatic Timers

**Items excluded from a building inspection:** • Water quality • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water heater relief valves are not tested

## Recommendations

### WATER HEATER \ Tank

**Condition:** • Safety pan and drain missing

**Implication(s):** Chance of water damage to contents, finishes and/or structure

## WATER HEATER \ Temperature/pressure relief valve

**Condition:** • TPR Discharge Tube Issues: The discharge tube should be as short and as straight as possible, ending at approximately 6" above the floor. The end of the tube should be uncapped, unthreaded, and readily visible.

Tube not straight; termination not visible. Have corrected by licensed plumber prior to occupancy.

**Location:** Water Heater

**Task:** Correct

**Time:** Immediate

## WASTE PLUMBING \ Venting system

**Condition:** • West basement vanity slow to drain; drainage rate increased when toilet was flushed. May indicate a venting issue. See notes elsewhere in this section regarding plumbing vents.

**Condition:** • [Automatic air vents](#)

**Implication(s):** Sewer gases entering the house

**Location:** Basement

## WASTE PLUMBING \ Sewage ejector pump

**Condition:** • [Odor](#)

Strong odor noted at ejector pump, north-east plumbing closet, basement. Presence of air admittance valve (AAV) raises questions of a possibly inadequate venting installation. No vents were observed at north side of roof. (may have been obscured by rooftop planters, etc.; presence of venting could not be confirmed). Have ejector and venting checked and repaired as needed by licensed plumbing contractor prior to closing.

**Implication(s):** Sewer gases entering the house

## FIXTURES AND FAUCETS \ Basin, sink and laundry tub

**Condition:** • Drain stop ineffective

**Implication(s):** Nuisance | Reduced operability

**Location:** Master bath and basement west

**Task:** Repair or replace

**Time:** Discretionary

## FIXTURES AND FAUCETS \ Toilet

**Condition:** • [Loose](#)


Loose toilets. Have licensed and insured plumbing contractor replace wax ring and re-seat loose toilet prior to closing.

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Sewage entering the house

**Location:** East basement bathroom, Master bathroom, Second floor west bathroom, First floor powder room

**Task:** Repair

**Time:** Immediate



## FIXTURES AND FAUCETS \ Shower stall

**Condition:** • Inoperative

Inoperative Rain Shower. Have checked and repaired as needed by licensed plumber prior to closing.

**Location:** Master bathroom shower stall

**Task:** Repair

**Time:** Immediate

## FIXTURES AND FAUCETS \ Shower stall enclosure

**Condition:** • [Leak](#)

Leak at master shower stall enclosure. Have repaired as needed by licensed shower stall specialist prior to use.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Master Bathroom

**Task:** Repair

**Time:** Immediate

## FIXTURES AND FAUCETS \ Whirlpool bath (Hydro-Massage Therapy Equipment) pump

**Condition:** • [Inoperative](#)

Inoperative; no access to motor or power source.

**Implication(s):** Equipment failure

**Location:** Basement Bathroom West

**Task:** Repair; install motor access panel

**Time:** Immediate

## Description

**Major floor finishes:** • [Carpet](#) • [Hardwood](#)

**Major wall and ceiling finishes:** • [Plaster/drywall](#)

**Windows:** • [Fixed](#) • [Casement](#) • Wood

**Glazing:** • [Double](#)

**Exterior doors - type/material:** • [French](#) • [Wood](#)

**Oven fuel:** • Gas

**Range fuel:** • Gas

**Appliances:** • Refrigerator • Range hood • Dishwasher • Waste disposal • Microwave oven

**Laundry facilities:** • Washer • Hot/cold water supply • Dryer • Vented to outside • 120-Volt outlet • Waste standpipe  
• Gas piping

## Limitations

**General:** • A HOME INSPECTION IS NOT A PEST INSPECTION. Insects, rodents, or wildlife of any kind are not included in this inspection. You are encouraged to retain an appropriately licensed pest inspector if you would like a pest inspection.

**Inspection limited/prevented by:** • Storage/furnishings • New finishes/paint • Storage in closets/cupboards

**Restricted access to:** • Cupboards and cabinets

**Not tested/not in service:** • Oven • Microwave • Dishwasher

**Not included as part of a building inspection:** • Telephone lines, cable television reception, antennas, digital cable, satellite dishes and all other electronic, digital, or fiber optic communication systems are not included in a home inspection. • Audio, Video, Computer, or Entertainment Systems • Outdoor Grills • Playsets

**Not included as part of a building inspection:** • Carbon monoxide detectors • Cosmetic issues • Appliances • Perimeter drainage tile around foundation, if any

**Cosmetics:** • No comment offered on cosmetic finishes

**Appliances:** • Appliances are not inspected as part of a building inspection • Appliances are not moved during an inspection

**Percent of foundation not visible:** • 100 %

**Basement leakage:** • Cannot predict how often or how badly basement will leak

## Recommendations

### FLOORS \ Ceramic tile, stone, marble, etc

**Condition:** • [Tiles cracked](#)

**Implication(s):** Cosmetic defects | Trip or fall hazard

**Location:** Basement (at media room stairway)

**Task:** Repair

**Time:** Discretionary


### WINDOWS \ Means of egress

**Condition:** • [Too small](#)

Second floor middle bedroom: windows are too small to conform to current national standards regarding rescue opening in case of emergency.

Basement bedrooms: Windows too high from finished floor surface to conform to current national standards for emergency rescue openings.

**Implication(s):** Restricted emergency exits



[Click on image to enlarge.](#)

### DOORS \ Hardware

**Condition:** • [Inoperable](#)

Second floor middle bedroom: Bathroom door fails to latch. Have adjusted as needed.

**Implication(s):** System inoperative or difficult to operate

### CARPENTRY \ Cabinets

**Condition:** • [Pieces missing or loose](#)

Missing/broken hardware, west basement bathroom vanity

**Implication(s):** Cosmetic defects | Damage or physical injury due to falling materials



## STAIRS \ Handrails

**Condition:** • [Missing](#)


Handrails and guardrails missing throughout. Guardrails at main stairway hazardous to children. All stairways should be reviewed and corrected as needed by licensed contractor prior to occupancy.

**Implication(s):** Fall hazard


**Location:** Throughout

**Task:** Correct


**Time:** Immediate



[Click on image to enlarge.](#)



Fall hazard: missing handrails



Missing hand- and guard-rails

## **APPLIANCES \ Dryer**

**Condition:** • Clean and service

Dryers and dryer vents should be thoroughly cleaned and serviced by licensed appliance specialist to improve efficiency and decrease fire risk.

**Condition:** • Foil Dryer Vent. Replace foil ducting material with rigid or corrugated semi-rigid metal duct. Most manufacturers specify the use of a rigid or corrugated semi-rigid metal duct, which provides maximum airflow. The flexible foil type duct can more easily trap lint and is more susceptible to kinks or crushing, which can greatly reduce the airflow. Have dryer cleaned and serviced, and rigid ductwork installed, by licensed appliance technician prior to closing.

**Location:** Basement

**Task:** Replace

**Time:** Immediate

**END OF REPORT**



# CPSC Fact Sheet

## Preventing Home Fires: Arc Fault Circuit Interrupters (AFCIs)

Problems in home wiring, like arcing and sparking, can cause fires in the home.

Arc fault circuit interrupters or AFCIs, can provide enhanced protection from fires resulting from these unsafe home wiring conditions.

Typical household fuses and circuit breakers do not respond to early arcing and sparking conditions in home wiring. By the time a fuse or circuit breaker opens a circuit to defuse these conditions, a fire may already have begun.

### AFCIs vs. GFCIs

AFCIs should not be confused with ground fault circuit interrupters or GFCIs. The popular GFCI devices are designed to provide protection from the serious consequences of electric shock.

While both AFCIs and GFCIs are important safety devices, they have different functions. AFCIs are intended to address fire hazards; GFCIs address shock hazards. Combination devices include both AFCI and GFCI protection in one unit.

### Should You Install AFCIs?

You may want to consider adding AFCI protection for both new and existing homes. Older homes with ordinary circuit breakers especially may benefit from the added protection against the arcing faults that can occur in aging wiring systems.

For more information about AFCIs, contact an electrical supply store, an electrician, or the manufacturer of the circuit breakers already installed in your home. Sometimes these components can be replaced with AFCIs in the existing electrical panel box.

Be sure to have a qualified electrician install AFCIs; do not attempt this work yourself. The installation involves working within electrical panel boxes that are usually electrically live, even with the main circuit breakers turned off.

Publication 5133  
R042012

U.S. Consumer Product Safety Commission, Bethesda, MD 20814 • (800) 638-2772 • [www.cpsc.gov](http://www.cpsc.gov) • [www.saferproducts.gov](http://www.saferproducts.gov)



## CPSC Safety Alert

### Are Your Window Coverings Safe?

The U.S. Consumer Product Safety Commission (CPSC) has identified window coverings with cords as one of the top five hidden hazards in the home. To prevent tragic child strangulations, CPSC recommends the use of cordless window coverings in all homes where children live or visit.

About once a month a child between 7 months and 10 years old dies from window cord strangulation and another child suffers a near strangulation. In recent years, CPSC has recalled over five million window coverings, including Roman shades, roller and roll-up blinds, vertical and horizontal blinds.

Strangulation deaths and injuries can occur anywhere in the house where a window covering with a cord is installed. Children can wrap window covering cords around their necks or can pull cords that are not clearly visible but are accessible and become entangled in the loops. These incidents happen quickly and silently.

#### Window covering cords present the following four deadly hazards:

**1**


##### **Pull Cords:**

Children can strangle when they wrap the cord around their necks or become trapped in the loop created when loose cords get entangled. Even if cleats are used to wrap excess pull cords, if installed within the child's reach, the cords above the cleat present a hazard.

**2**

##### **Looped Bead Chains or Nylon Cords:**

Children can strangle in the free-standing loops.





## CPSC Safety Alert

3

### Inner Cords of Roman Shades

- Children can pull out an exposed inner cord on the back side of Roman shades, wrap it around their necks and strangle.
- Children can place their necks in the opening between the fabric and cord and strangle.



4

### Lifting Loops of Roll-up Blinds

- If the lifting loops (that raise and lower the blinds) slide off the side of the blind, they form a free-standing loop in which a child can become entangled and strangle.
- Children can place their necks between the lifting loop and the roll-up blind material and strangle.



**CPSC offers the following safety tips to prevent deaths and injuries associated with window covering cords:**

- Examine all shades and blinds in the home. CPSC recommends the use of cordless window coverings in all homes where children live or visit. Make sure there are no accessible cords on the front, side, or back of the product.
- Do not place cribs, beds, and furniture close to the windows because children can climb on them and gain access to the cords.
- Make loose cords inaccessible.
- If the window shade has looped bead chains or nylon cords, install tension devices to keep the cord taut.

**Note:** Most window blinds sold prior to November 2000 have inner cords (for raising the slats of the blinds) that can be pulled by a child and form a loop in which the child's neck can entangle. Consumers should immediately repair these types of blinds. For a free repair kit, call the Window Covering Safety Council at 800-506-4636 or visit [windowcoverings.org](http://windowcoverings.org). Consumers should know that WCSC's retrofit kits do not address the dangling pull cord hazard associated with many common window blinds.

5009-0413




## CPSC Safety Alert

### Overheated Clothes Dryers Can Cause Fires

Fires can occur when lint builds up in the dryer or in the exhaust duct. Lint can block the flow of air, cause excessive heat build-up, and result in a fire in some dryers.

To help prevent fires:

- **Clean the lint screen/filter before or after drying each load of clothes.** If clothing is still damp at the end of a typical drying cycle or drying requires longer times than normal, this may be a sign that the lint screen or the exhaust duct is blocked.
- **Clean the dryer vent and exhaust duct periodically.** Check the outside dryer vent while the dryer is operating to make sure exhaust air is escaping. If it is not, the vent or the exhaust duct may be blocked. To remove a blockage in the exhaust path, it may be necessary to disconnect the exhaust duct from the dryer. Remember to reconnect the ducting to the dryer and outside vent before using the dryer again.
- **Clean behind the dryer, where lint can build up.** Have a qualified service person clean the interior of the dryer chassis periodically to minimize the amount of lint accumulation. Keep the area around the dryer clean and free of clutter.
- **Replace plastic or foil, accordion-type ducting material with rigid or corrugated semi-rigid metal duct.** Most manufacturers specify the use of a rigid or corrugated semi-rigid metal duct, which provides maximum airflow. The flexible plastic or foil type duct can more easily trap lint and is more susceptible to kinks or crushing, which can greatly reduce the airflow.
- **Take special care when drying clothes that have been soiled with volatile chemicals** such as gasoline, cooking oils, cleaning agents, or finishing oils and stains. If possible, wash the clothing more than once to minimize the amount of volatile chemicals on the clothes and, preferably, hang the clothes to dry. If using a dryer, use the lowest heat setting and a drying cycle that has a cool-down period at the end of the cycle. To prevent clothes from igniting after drying, do not leave the dried clothes in the dryer or piled in a laundry basket.



Publication 5022 062003 022012

U.S. CONSUMER PRODUCT SAFETY COMMISSION • (800) 638-2772 • www.cpsc.gov • www.SaferProducts.gov